


The system with calibration the display show E\*\*\* .

The first time show "E000". Next time maybe show "E100" or "E200" according what date set.

Pls check below informations about how to calibrate

1.First,please check below red circle,Super Chlor turn off



2.Then find "E\*\*\*" on the display board,the first time show "E000"



3.Dial the chlorine output to 100% first,then dial 100% to 50%,when see "E" is flashing, by dial 0%-50% or 50% to 100% to set.

The system can be calibrate from " -E100" to "-E800 "and "E100" to "E800".

"E100" means salt level add 100,"-E100" means minus 100.



4. Press "System Status" ,pls check below red circle area



5. When see "--AA", finished set

